

MACHINE SHOP

RELATED COURSE OF STUDY IN MACHINE SHOP PRACTICE

TEXT: - Machine Shop Training - Krar & St Amand

<u>TOPIC OF LESSON</u>	<u>CH.</u>	<u>PAGE</u>
INTRODUCTION AND COURSE OUTLINE		
Organization of the Machine Shop	2	3-4
Safety Regulations	3	5-6
<u>MEASUREMENT</u>	4	7-14
The steel rule		7- 8
Decimal System (the micrometer .001")		10-12
The Vernier principle .0001"		13
The Vernier Caliper - construction		13-14
- graduation		14
<u>LAYOUT</u>	5	17-24
Definition; preparing the surface		17
Use of Layout tools; layout table		17
Layout operations		18-24
<u>^SELECTION AND USE OFFHAND TOOLS</u>	7	34-46
Trie" macfnnist's vise (safety jaws)		34-35
The hammer; hand hacksaw		35-37
Chisels—common types; sharpening		37-38
Files; filing		38-40
Taps in a set—National Thread Series		41
Calculate the Tap Drill size		42-43
Classification of twist drills	62 &	162
Tapping a hole with tap and tap wre, ch		43
Threading dies; threading with stock & die		43-44
Metal fasteners; wrenches		44-47
<u>THE POWER SAW</u>	8	49-56
Cut off Saw - parts; saw blades		49-50
Contour cutting Bandsaw		51
Welding a saw blade		53
ASSIGNMENT QUESTIONS		57
<u>THE DRILL PRESS</u>	9	
DrfTTpress parts		
Drill holding devices		
Twist drill parts		
Systems of drill sizes		
Speeds and feeds of drills		
Cutting oils and cutting compounds		

NO.	TOPIC OF LESSON	CH.	PAGE
28.	Combination drill and countersink		64-65
29.	Work holding devices		65-67
30.	Drill to a layout		67-68
31.	Countersinking; counterboring		69
32.	Reaming; boring; spotfacing		69-70
	<u>THE LATHE</u>	10	73-106
33.	Identification of main parts; function of each		73-75
34.	Select speeds & feeds		76
35.	Calculate spindle speed		77-78
36.	Work-holding devices		79-82
37.	Alignment of lathe centres		82
38.	End facing		84
39.	Decimal equivalents; Micrometer collars		85
40.	Basic turning operations - rough turning - finish turning		85 86
41.	Standard Tapers used in industry		90
42.	Taper calculations		90-91
43.	Taper turning - offset tailstock method		91-92
44.	Turn tapers and angles -- using compound rest		92
45.	Fit a taper to a gauge		93-94
	<u>LATHE CHUCKS - UNIVERSAL, INDEPENDENT</u>	10	94-98
46.	Chucking operations		
	<u>STANDARD THREAD FORMS</u>	10	99-100
47.	Thread terms (parts of a thread)		99
48.	Thread formulae, calculations		100-101
49.	Thread cutting on lathe		101-105
50.	Measuring the thread for size		106
51.	Tapping a hole by power -- drill press — Lathe		70 98
	<u>NON-FERROUS METALS USED IN INDUSTRY</u>	6	30
52.	Turning soft metals		
53.	Drilling and tapping non-ferrous metals		
54.	Reamers		
55.	Reaming non-ferrous metals		
	<u>THE PEDESTAL GRINDER - PARTS</u>	13	143
	- <u>DRESS AND TRUE A WHEEL</u>		144-145
56.	Sharpen chisels		
57.	Sharpen lathe tool bits		145-146
58.	Sharpen twist drills (Page 61)		147