

COURSE OUTLINE: MTF109 - OXY FUSION/BRAZE WEL

Prepared: Dave Holley

Approved: Corey Meunier, Chair, Technology and Skilled Trades

Course Code: Title	MTF109: OXY FUSION AND BRAZE WELDING	
Program Number: Name	4051: METAL FABRICATION 4053: WELDING TECHNIQUES	
Department:	IRONWKR APPR./WELDING RELATED	
Semesters/Terms:	20F	
Course Description:	This course teaches students how to safely set up Oxyfuel equipment, how to safely use the equipment, torch cut various thickness of metal materials, fusion weld with or without filler metal, and braze. Techniques needed to weld and cut, will develop hand eye skills required to be a welder.	
Total Credits:	2	
Hours/Week:	2	
Total Hours:	30	
Prerequisites:	There are no pre-requisites for this course.	
Corequisites:	There are no co-requisites for this course.	
Substitutes:	MTF136	
Vocational Learning Outcomes (VLO's) addressed in this course: Please refer to program web page	VLO 3 Prepare materials by utilizing fabrication machinery and equipment. VLO 5 Understand and use a variety of destructive and non-destructive methods to test welds.	
for a complete listing of program outcomes where applicable.	 VLO 7 Complete all work in compliance with health and safety legislation and prescribed organizational practices and procedures to ensure safety of self and others. VLO 8 Work responsibly and effectively in accordance with government safety regulations, manufacturer's recommendations and approved industry standards. 	
Essential Employability Skills (EES) addressed in this course:	EES 5 Use a variety of thinking skills to anticipate and solve problems. EES 10 Manage the use of time and other resources to complete projects. EES 11 Take responsibility for ones own actions, decisions, and consequences.	
Course Evaluation:	Passing Grade: 50%, D A minimum program GPA of 2.0 or higher where program specific standards exist is required for graduation.	
Other Course Evaluation & Assessment Requirements:	1.Late hand in penalties will be -10% per day. 2.If a student misses a test, he/she must have a valid reason (i.e. medical or family emergency documentation shall be required). In addition, the instructor MUST be notified PRIOR to the test sitting. If this procedure is not followed the student will receive a mark of zero on the test with	

In response to public health requirements pertaining to the COVID19 pandemic, course delivery and assessment traditionally delivered in-class, may occur remotely either in whole or in part in the 2020-2021 academic year.



SAULT COLLEGE | 443 NORTHERN AVENUE | SAULT STE. MARIE, ON P6B 4J3, CANADA | 705-759-2554

MTF109: OXY FUSION AND BRAZE WELDING Page 1 no make-up option.

- 3.Re-writes are NOT allowed for any written assignment, quiz or test.
- 4.Course attendance is mandatory. Any student that is not present for the first 3 classes in each course, will be deemed to have not completed the required safety orientation for the course and will not be permitted to continue. One percent (1 %) per hour will be deducted from the final course grade for unexcused* absence. Any unexcused attendance beyond 15% of the total allocated course hours will result in the student receiving a failing grade for the course.

Valid reasons would include:

Course Outcome 1

Doctors note

Family Death or Serious Illness supported by a written note.

Unexcused absence* will be determined in a case by case basis by the instructor of each course.

Learning Objectives for Course Outcome 1

Course Outcomes and Learning Objectives:

A trade curriculum that has 1. Identify equipment and procedures required to assure been designed to provide personal safety while engaged in shop activities. students with a combination - Potential Elements of the Performance: of theoretical knowledge - identify proper work boots, gloves and eye protection and hands on skill in relation - identify recommended fabrics and materials for personal to the safe use and protective clothing operation of Oxy\Fuel - understand the general organization and layout of the welding welding, cutting and heating shop facility equipment. - locate and identify shop lighting and ventilation controls - locate and identify emergency exits - identify and select proper shades of welding / cutting lens - identify, select and adjust helmets for proper fit and vision - understand procedures for evacuation of shop areas in the case of emergencies 2. Identify oxyacetylene cutting and welding equipment / accessories including their construction, operation, assembly and disassembly Potential Elements of the Performance: - cylinders - identification - general construction - pressure regulators manual valves - manifold systems - gages and hoses - torch body

- tips for cutting, heating, welding

- check equipment for safe operating condition

Potential Elements of the Performance:

3. Identify, describe and demonstrate the theory of

cutting attachmentsflashback arrestors

oxyacetylene cutting.

In response to public health requirements pertaining to the COVID19 pandemic, course delivery and assessment traditionally delivered in-class, may occur remotely either in whole or in part in the 2020-2021 academic year.

SAULT COLLEGE | 443 NORTHERN AVENUE | SAULT STE. MARIE, ON P6B 4J3, CANADA | 705-759-2554

MTF109: OXY FUSION AND BRAZE WELDING Page 2

- set up equipment for oxyacetylene cutting
- select tip size and set cutting pressures for a given thickness of metal
- check equipment for safe operation
- pressurize, ignite, adjust and safely operate a cutting torch
- perform typical flame cutting operations to include
- square cut c/w re-start
- bevel cut c/w re-start
- piercing and making holes
- prepare plate edges for butt welding
- 4. Demonstrate the ability to recognize weld faults and control distortion.

Potential Elements of the Performance:

- name the factors that determine weld quality
- list the properties of a good weld
- identify and sketch three types of oxyacetylene welding flames
- name the factors that determine tip selection
- state the purpose of using a filler rod
- list the factors that determine filler rod selection
- state the cause and methods of control for welding faults
- state the cause and methods of control for distortion
- 5. Demonstrate the ability to deposit sound weld beads, tack welds and butt joints with filler rod using fusion and brazing techniques.
- Potential Elements of the Performance:
- set up equipment for oxyacetylene welding
- select tip size and set welding pressures for a given thickness of metal
- pressurize, ignite, adjust and safely operate a welding torch
- check equipment for safe operation
- deposit weld beads on mild steel plate with filler rod
- prepare butt joints to specification for welding
- tack weld joints to maintain alignment
- butt weld mild steel plate in the flat, horizontal and vertical position with filler rod.

Page 3

Evaluation Process and Grading System:

Evaluation Type	Evaluation Weight
Braze Welding	35%
Cutting	30%
Fusion Welding	35%

Date:

June 11, 2020

Addendum:

Please refer to the course outline addendum on the Learning Management System for further information.

In response to public health requirements pertaining to the COVID19 pandemic, course delivery and assessment traditionally delivered in-class, may occur remotely either in whole or in part in the 2020-2021 academic year.



SAULT COLLEGE | 443 NORTHERN AVENUE | SAULT STE. MARIE, ON P6B 4J3, CANADA | 705-759-2554

In response to public health requirements pertaining to the COVID19 pandemic, course delivery and assessment traditionally delivered in-class, may occur remotely either in whole or in part in the 2020-2021 academic year. SAULT COLLEGE | 443 NORTHERN AVENUE | SAULT STE. MARIE, ON P6B 4J3, CANADA | 705-759-2554

MTF109: OXY FUSION AND BRAZE WELDING Page 4